


凡 例

- 建物
- ① 未とりこなし建物
- ② 危険建物
- ③ 借用建物
- ④ 一時使用建物
- ⑤ 屋外教育環境
整備事業によるもの

方位



(北に印刷を付す)



令和5年度 公立学校施設等の総括表(中学校)

都道府県名 山梨県

設置者名 富士川町

学校所在地 南巨摩郡富士川町天神中條991-1

ふりがな ますほ 増穂中学校

整理番号 0006

Table with school identification information including school code (C19364104), school district (4), and school type (1).

Table with enrollment numbers for the current and previous years, including total enrollment (368) and special support enrollment (15).

Table with school type and facility details, including building count (6082) and total area (13289).

Main table section 1: Facility status and area calculations, including total area (4489) and R-calculated area (5508).

Table with area breakdown for various facility types, including R-calculated area (5508).

Main table section 2: Facility status and area calculations, including total area (1138) and R-calculated area (1355).

Table with area breakdown for various facility types, including R-calculated area (1355).

Main table section 3: Facility status and area calculations, including total area (1132) and R-calculated area (1694).

Table with area breakdown for various facility types, including R-calculated area (1694).

Table with area breakdown for various facility types, including R-calculated area (1694).

Table with area breakdown for various facility types, including R-calculated area (1694).

Table with facility status and area calculations, including total area (1132) and R-calculated area (1694).

Table with area breakdown for various facility types, including R-calculated area (1694).

Table with area breakdown for various facility types, including R-calculated area (1694).

Table with area breakdown for various facility types, including R-calculated area (1694).

Table with area breakdown for various facility types, including R-calculated area (1694).

令和 5 年度 公立学校等建物の棟別面積表 (その 2)

様 式 2

当該学校の設置年度 S45	設置者名 富士川町	増穂中学校	相手方の学校名
①識別コード L	②都道府県番号 19	③学校調査番号 3641	④冬季分校番号
			整理番号 0006

棟番号	建築物区分番号	建造年月	学 部	保 有 面 積	耐 力 度 点 数	耐 震 基 準	耐 震 先 行 診 断 状 況	診 断 年 度	改 修 状 況	耐 震 性 能		大規模改造年度	改 修 履 歴		備考	
										Is 値	CT X SD 値		q 値	内部改修		外部改修
⑤	⑥⑦⑧⑨⑩	⑪⑫	⑬	⑭	A	Y K L	P	M		C	T	⑮	Φ	X	□	
001	校R4S4604	2138				12	S5610.840.84	H23	2	2	2		2	2	2	備考 その 2
002	校R4S4609	3117				12	S5610.840.84	H23	2	2	2		2	2	2	山
0031	校S1S4704															
0032	校S1S5809															
004	校S1S4609	11				15										
007	校R1S4610	243				12	H2112.210.92		1	2	1					
014	屋S1S5809															
015	部R1H0401	247				2							2	2	2	
016	校R1H1510	10				2										
017	屋S1H1909	1355				2										

コード説明

①耐震基準 旧耐震基準.....1 新耐震基準.....2	K診断状況 優先度調査.....0 S造又は上記以外の診断.....4 R造の第一次診断.....1 未実施.....5 R造の第二次及び第三次診断.....2 屋体のS造.....3	P改修状況 改修済み.....1 改修中.....2 未改修.....3 未改修のうち当年度実施予定.....4
-------------------------------------	--	--